



Stepan Company
4600 US HIGHWAY 421 N
Wilmington, NC 28401

April 22, 2022

Certified Mail – Return Receipt Requested
7015 1520 0003 6092 2384

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

RE: Transfer Notification

Dear Sir/Madam:

In fulfillment of the requirements of 10 CFR 31.5(c)8, we hereby notify you that on 4/13/22 Stepan transferred the self-luminous exit signs listed on the attached spreadsheets to SRB Technologies Inc. 2580 Landmark Dr., Winston-Salem, NC 27103 North Carolina License# 034-0534-2. As required, for the signs listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you have any questions, please contact Elizabeth Meyer at elizabeth.meyer@stepan.com or 910-341-5515.

Sincerely,

A handwritten signature in dark ink, appearing to read "Phillip Cline", written over a light-colored rectangular background.

Phillip Cline
Site Manager, Authorized Signatory
Stepan Company

cc:

William Johnson
NC Radiation Protection Section
1645 Mail Service Center
Raleigh, NC 27699-1600



RGA #:
DATE ISSUED:
EXPIRATION DATE:

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. **DO NOT REMOVE THE LABEL FROM THE SIGN.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

INSTALLATION SITE NAME: STEPAN WILMINGTON SITE

BOX # 1 OF 2

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Isolite Corp.	2040-01	10-7618	3/2010	10 yr
2.	Isolite Corp.	2040-01	10-7619	3/2010	10 yr.
3.	Isolite Corp.	2040-01	10-7621	3/2010	10 yr.
4.	Isolite Corp.	2040-01	10-7620	3/2010	10 yr.
5.	Euelite	SLX60	431109	N/A	7.5
6.					
7.					
8.					
9.					
10.					

230
TB9

Describe any damaged units:
Please email pictures of damaged signs to Veolia.

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature: Title: ENV. SPECIALIST

Print Name: CHARITY COURY Date: 4/13/22

VEOLIA USE ONLY, FIELD SERVICES



VEOLIA USE ONLY

 RGA #:
 DATE ISSUED:
 EXPIRATION DATE:

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. DO NOT REMOVE THE LABEL FROM THE SIGN. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

 INSTALLATION SITE NAME: STEPAN WILMINGTON SITE

 BOX # 2 OF 2

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Eveolite	SLX60	431108	NA	2.5 7.5
2.	Isolite	SLX60	10-3871	02/2010	0.230TBq
3.	Eveolite	SLX60	431107	N/A	7.5
4.	Eveolite	SLX60	426312	2007	7.5
5.	Isolite	SLX60	1203965	07/12	0.230TBq
6.	Isolite	SLX60	103897	02/2010	0.230TBq
7.	Isolite	SLX60	103881	02/2010	0.230TBq
8.	Isolite	SLX60	1203967	07/12	0.230TBq
9.	Eveolite	SLX60	426346	8/2007	7.5
10.	Eveolite	SLX60	430091	9/2007	7.5

Describe any damaged units:
 Please email pictures of damaged signs to
 Veolia.

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION	
Generator Signature: <u>[Signature]</u>	Title: <u>ENV. SPECIALIST</u>
Print Name: <u>CHARITY COURT</u>	Date: <u>4/13/22</u>