



October 3, 2011

Mr. Nick Berliner
Cabrera Services, Inc.
473 Silver Lane
East Hartford, CT 06118

Re: ALS Workorder: 11-08-251
Project Name: DHS-EML
Project Number: 07-3080.01

Dear Mr. Berliner:

One water sample, twelve soil samples and twelve leachate samples were received from Cabrera Services, Inc. on August 18, 2011. The samples were scheduled for the following analyses:

PCBs	pages 1-183
Metals	pages 1-145
Ignitability	pages 1-24
Pesticides	pages 1-139
Inorganics	pages 1-33
Herbicides	pages 1-130
Paint Filter	pages 1-14
GC/MS Volatiles	pages 1-258
GC/MS Semivolatiles	pages 1-279

The results for these analyses are contained in the enclosed reports.

Thank you for your confidence in ALS Environmental. Should you have any questions, please call.

Sincerely,

ALS Environmental
Lance Steere
Senior Project Manager

LRS/eg
Enclosure(s): Report, CD and EDD

ALS Environmental -- FC

Sample Number(s) Cross-Reference Table

OrderNum: 1108251

Client Name: CABRERA SERVICES, INC.

Client Project Name: DHS-EML

Client Project Number: 07-3080.01

Client PO Number: 09-1281

Client Sample Number	Lab Sample Number	COC Number	Matrix	Date Collected	Time Collected
SN 2	1108251-1		SOIL	16-Aug-11	10:47
SN 3	1108251-2		SOIL	16-Aug-11	13:25
SN 4	1108251-3		SOIL	17-Aug-11	10:14
SN 5	1108251-4		SOIL	16-Aug-11	10:30
SN 7	1108251-5		SOIL	17-Aug-11	12:45
SN 8	1108251-6		SOIL	16-Aug-11	11:07
SN 11	1108251-7		SOIL	16-Aug-11	12:35
SN 12	1108251-8		SOIL	17-Aug-11	12:20
SN 13	1108251-9		SOIL	17-Aug-11	11:00
SN 14	1108251-10		SOIL	17-Aug-11	10:38
SN 15	1108251-11		SOIL	16-Aug-11	11:21
SN 16	1108251-12		SOIL	16-Aug-11	13:16
TRIP BLANK	1108251-13		WATER	16-Aug-11	
SN 2	1108251-14		LEACHAT	16-Aug-11	10:47
SN 3	1108251-15		LEACHAT	16-Aug-11	13:25
SN 4	1108251-16		LEACHAT	17-Aug-11	10:14
SN 5	1108251-17		LEACHAT	16-Aug-11	10:30
SN 7	1108251-18		LEACHAT	17-Aug-11	12:45
SN 8	1108251-19		LEACHAT	16-Aug-11	11:07
SN 11	1108251-20		LEACHAT	16-Aug-11	12:35
SN 12	1108251-21		LEACHAT	17-Aug-11	12:20
SN 13	1108251-22		LEACHAT	17-Aug-11	11:00
SN 14	1108251-23		LEACHAT	17-Aug-11	10:38
SN 15	1108251-24		LEACHAT	16-Aug-11	11:21
SN 16	1108251-25		LEACHAT	16-Aug-11	13:16



1108251

ALS Global Chain-of-Custody Record

225 Commerce Drive
Fort Collins, CO 80524
Phone: (800) 443-1511

Customer Information		Project Information		Analyses / Method Requested	
Project Name	DHS 07-3080.01	Purchase Order	09-1281	A. TCLP RCRA VOCs	
Quote#		Work Order		B. TCLP RCRA SVOCs	
Company	Cabrera Services, Inc.	Bill To	Cabrera Services, Inc.	C. TCLP RCRA Metals	
Send Report To:	Nicholas Berliner	Invoice Attn:	Accounting	D. RCRA Pesticides/Herbicides (8081)	
Address:	473 Silver Lane	Address:	473 Silver Lane	E. PCBs (8082)	
City/State/Zip	East Hartford, CT 06118	City/State/Zip	East Hartford, CT 06118	F. Ignitability/corrosivity/reactivity/paint filter	
Phone	(860) 569-0095	Phone	(860) 569-0095	G. Initial gamma Spec (no ingrowth)	
Fax	(860) 569-0277	Fax	(860) 569-0277	H. Gamma Spec. (E 901.1 M)	
				I. Alpha Spec for U (ASTM D3972-90)	
				J. Ra-226 by emanation (E 903.1 M)	

Chain of Custody

Shipment Method:	Federal Express	Airbill Nos.:	7950 9125 3210	Required Turnaround:	30 days
Relinquished by:	Nicholas Berliner	Date:	8/17/11	Relinquished by:	
Company Name:	CABRERA SERVICES, INC.	Time:	1920	Company Name:	
Received by:	Lauren Chinn	Date:	8/18/11	Received by:	
Company Name:	ALS	Time:	1010	Company Name:	

Sx No.	Sample Description	Sample Date	Sample Time	Sample Matrix	Container Type	Preservative	No. of Bottles	A	B	C	D	E	F	G	H	I	J	Comments	
1	SN 2 (1)	2011-08-16	1047	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(14)	
2	SN 3 (2)	2011-08-16	1325	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(15)	
3	SN 4 (3)	2011-08-17	1014	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(16)	
4	SN 5 (4)	2011-08-16	1030	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(17)	
5	SN 7 (5)	2011-08-17	1245	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(18)	
6	SN 8 (6)	2011-08-16	1107	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(19)	
7	SN 11 (7)	2011-08-16	1235	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(20)	
8	SN 12 (8)	2011-08-17	1220	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(21)	
9	SN 13 (9)	2011-08-17	1100	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(22)	
10	SN 14 (10)	2011-08-17	1038	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(23)	
11	SN 15 (11)	2011-08-16	1121	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(24)	
12	SN 16 (12)	2011-08-16	1316	SOIL	B	ICE	2	X	X	X	X	X	X	X	X	X	X	(25)	

NMB 8/17/11
B = 4-gallon ziplock bag - 8-oz soil jar

M = marinelli beaker



CONDITION OF SAMPLE UPON RECEIPT FORM

Client: Cabrera
Project Manager: LRS

Workorder No: 1108251
Initials: LAS Date: 8/18/11

1. Does this project require any special handling in addition to standard Paragon procedures?		YES	<input checked="" type="radio"/> NO
2. Are custody seals on shipping containers intact?	NONE	<input checked="" type="radio"/> YES	NO
3. Are Custody seals on sample containers intact?	<input checked="" type="radio"/> NONE	YES	NO
4. Is there a COC (Chain-of-Custody) present or other representative documents?		<input checked="" type="radio"/> YES	NO
5. Are the COC and bottle labels complete and legible ?		<input checked="" type="radio"/> YES	NO
6. Is the COC in agreement with samples received? (IDs, dates, times, no. of samples, no. of containers, matrix, requested analyses, etc.)		YES	<input checked="" type="radio"/> NO *
7. Were airbills / shipping documents present and/or removable?	DROP OFF	<input checked="" type="radio"/> YES	NO
8. Are all aqueous samples requiring preservation preserved correctly ? (excluding volatiles)	<input checked="" type="radio"/> N/A	YES	NO
9. Are all aqueous non-preserved samples pH 4-9 ?	<input checked="" type="radio"/> N/A	YES	NO
10. Is there sufficient sample for the requested analyses?		<input checked="" type="radio"/> YES	NO
11. Were all samples placed in the proper containers for the requested analyses?		<input checked="" type="radio"/> YES	NO
12. Are all samples within holding times for the requested analyses?		<input checked="" type="radio"/> YES	NO
13. Were all sample containers received intact ? (not broken or leaking, etc.)		<input checked="" type="radio"/> YES	NO
14. Are all samples requiring no headspace (VOC, GRO, RSK/MEE, Rx CN/S, radon) headspace free? Size of bubble: <u> </u> < green pea <u> </u> > green pea	N/A	<input checked="" type="radio"/> YES	NO
15. Do perchlorate LCMS-MS samples have headspace ? (at least 1/3 of container required)	<input checked="" type="radio"/> N/A	YES	NO
16. Were samples checked for and free from the presence of residual chlorine ? (Applicable when PM has indicated samples are from a chlorinated water source; note if field preservation with sodium thiosulfate was not observed.)	<input checked="" type="radio"/> N/A	YES	NO
17. Were the samples shipped on ice ?		<input checked="" type="radio"/> YES	NO
18. Were cooler temperatures measured at 0.1-6.0°C? IR gun used*: <input checked="" type="radio"/> #2 <input type="radio"/> #4 <input type="radio"/> RAD ONLY		<input checked="" type="radio"/> YES	NO
Cooler #: <u>1</u>			
Temperature (°C): <u>5.0</u>			
No. of custody seals on cooler: <u>1</u>			
External µR/hr reading: <u>14</u>			
Background µR/hr reading: <u>12</u>			
Were external µR/hr readings ≤ two times background and within DOT acceptance criteria? YES / NO / NA (If no, see Form 008.)			

Additional Information: PROVIDE DETAILS BELOW FOR A NO RESPONSE TO ANY QUESTION ABOVE, EXCEPT #1 AND #16.

* Trip Blank (2, 40ml vials) not listed on COC.
Added as sample # 1108251-13 (bottles 1 & 2)

Proceed with analysis

If applicable, was the client contacted? YES / NO / NA Contact: Mindy B. Date/Time: 8/22

Project Manager Signature / Date: [Signature] 8/22/11

From: (860) 916-6091
Nicholas Berliner - DHS
CABRERA SERVICES
201 Varick Street
c/o Al Crescenzi, 5th floor, DHS
EAST HARTFORD, NY 10014

Origin ID: UTOA



201104290225

Ship Date: 17AUG11
ActWgt: 40.0 LB
CAD: 4239785/NET3180

Dims: 36 X 18 X 18 IN

1108251 14
1 -

SHIP TO: (970) 490-1511

BILL SENDER

Lance Steere
ALS Laboratories
225 COMMERCE DR

FORT COLLINS, CO 80524

Delivery Address Bar Code





Ref # 07-3080.01 Task 005
Invoice #
PO #
Dept #

THU - 18 AUG A2
PRIORITY OVERNIGHT

TRK# 7950 9125 3210
0201

NJ FTCA

80524
CO-US
DEN



50FG1/EEE7/F#F4

After printing this label:

- Use the 'Print' button on this page to print your label to your laser or inkjet printer.
- Fold the printed page along the horizontal line.
- Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

5.0