

FEDERAL NOTIFICATION LETTER

Thursday, April 3rd 2025

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Oakhurst Gardens
600 W Minnetrista BLVD
Muncie, IN 47303

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)	4/14/2025
--	-----------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Randy Gowin
Signature:	Randy Gowin
Phone Number:	765-287-3565

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

SALES ORDER: 2371523
 CASE #: 000236984
 BOX: 1 of 1
 REF #: 944

RGA #: 221182 / Issued: 4/3/25
 UCN: 5S51389T-1U62357V
 FedEx Tracking #: 880291775967
 Box 1 of 1 / Ref #: 944

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice. Please complete the lines below that contain numbers.

MFR	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1 Isolite	2000	A58738	Aug - 1995	7.5
2 Isolite	2000	A58737	Aug - 1995	7.5
3 Isoite	2000	A58739	Aug - 1995	7.5
4 Isolite	2000	A58740	Aug - 1995	7.5
Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com				

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION			
Generator Signature:	<i>Randy Gowin</i>	Title:	Director of Maintenance
Print Name:	Randy Gowin	Date:	April 1, 2025

VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX			
Date Received:	04/03/2025	Checked in by:	<i>Abigail Koepke</i>

