


Indian Point 3 3Q/2010 Performance Summary









Last Modified: October 25, 2010

Residual Heat Removal System

Cooling Water Systems (G)

Legend: R=Red W=White T=Thresholds under development N=Not Applicable Y=Yellow G=Green I=Insufficient data to calculate PI U=Unique Design





Miscellaneous findings

Additional Inspection & Assessment Information

- Assessment Reports/Inspection Plans:
 - 3Q/2010
 - 2Q/2010
 - 1Q/2010
 - 4Q/2009
- **Cross Reference Of Assessment Reports**

- List of Inspection Reports (IR)
- List of Security IR Cover Letters
- List of Assessment Letters/Inspection Plans
- **Baseline Inspection Completion Information**

Last Modified: November 3, 2010