

## McGuire 1 3Q/2013 Performance Summary






Last Modified: November 1, 2013

Heat Removal System (G)

Residual Heat Removal System

Cooling Water Systems (G) Legend: R=Red W=White GTG=Greater Than Green I=Insufficient Data to Calculate PI U=Unique Design
Y=Yellow G=Green T=Thresholds under development N=Not Applicable D=Discrepant



- Assessment Reports/Inspection Plans:
  - 3Q/2013
  - 2Q/2013
  - 10/2013
  - 4Q/2012
- Cross Reference Of Assessment Reports

- List of Inspection Reports (IR)
- List of Security IR Cover Letters
- List of Assessment Letters/Inspection Plans
- Baseline Inspection Completion Information

Last Modified: December 3, 2013

Action Matrix Summary | Inspection Findings Summary | PI Summary | Reactor Oversight Process